Online Research @ Cardiff

This is an Open Access document downloaded from ORCA, Cardiff University's institutional repository: <https://orca.cardiff.ac.uk/id/eprint/70271/>

This is the author's version of a work that was submitted to / accepted for publication.

Citation for final published version:

Crivelli, Davide ORCID: <https://orcid.org/0000-0002-1573-5726>, Guagliano, Mario, Eaton, Mark ORCID: <https://orcid.org/0000-0002-7388-6522>, Pearson, Matthew ORCID: <https://orcid.org/0000-0003-1625-3611>, Al-Jumaili, Safaa, Holford, Karen ORCID: <https://orcid.org/0000-0002-3239-4660> and Pullin, Rhys ORCID: <https://orcid.org/0000-0002-2853-6099> 2015. Localisation and identification of fatigue matrix cracking and delamination in a carbon fibre panel by acoustic emission. Composites Part B: Engineering 74 , pp. 1-12. 10.1016/j.compositesb.2014.12.032 file

Publishers page: <http://dx.doi.org/10.1016/j.compositesb.2014.12.03...>
<<http://dx.doi.org/10.1016/j.compositesb.2014.12.032>>

Please note:

Changes made as a result of publishing processes such as copy-editing, formatting and page numbers may not be reflected in this version. For the definitive version of this publication, please refer to the published source. You are advised to consult the publisher's version if you wish to cite this paper.

This version is being made available in accordance with publisher policies.

See

<http://orca.cf.ac.uk/policies.html> for usage policies. Copyright and moral rights for publications made available in ORCA are retained by the copyright holders.

Localisation and Identification of Matrix Cracking and Delamination in a Carbon Fibre Panel under Fatigue Loading using Acoustic Emission

Davide Crivelli^a, Mario Guagliano^a, Mark Eaton^b, Matthew Pearson^b, Safaa Al-Jumaili^b, Karen Holford^b, Rhys Pullin^b

^aPolitecnico di Milano, Department of Mechanical Engineering, via La Masa 1, 20156 Milano, Italy
davide.crivelli@polimi.it
mario.guagliano@polimi.it

^bCardiff School of Engineering, Cardiff University, Queen's Building, The Parade, Cardiff CF24 3AA, Wales, UK
eatonm@cardiff.ac.uk
pearsonmr@cardiff.ac.uk
Al-JumailiSK@cardiff.ac.uk
holford@cardiff.ac.uk
pullinr@cardiff.ac.uk

Abstract

The use of Acoustic Emission (AE) as a Structural Health Monitoring (SHM) technique is very attractive due to its ability to detect not only damage sources in real-time but also to locate them. To demonstrate the AE capabilities on known damage modes, a carbon fibre panel was manufactured with cut fibres in a central location, and subjected to fatigue loading to promote matrix cracking. AE signals were located within the crack area; next, a delamination within the panel using an impact was created. Again, AE signals detected under fatigue loading from this area were located and used for further analysis. The application of an unsupervised neural network based classification technique successfully separated the two damage mechanisms. The results obtained allowed a more detailed understanding of matrix cracking and delamination sources of AE in carbon fibre laminates.

Keywords: A. Carbon fibre, A. Laminates, C. Damage mechanics, D. Acoustic emission, Artificial damage

1. Introduction

The increasing use of composite materials in those sectors that require a particular attention on weight reduction, while keeping the same safety and reliability levels of metallic structures, will require these structures to be equipped with an on-board sensing method capable of detecting damage. This family of techniques goes under the name of Structural Health Monitoring (SHM), comprising all those systems, that monitor, either continuously or at specific moments, the health status of a material, giving indication to the user about damage developing, damage severity and eventually damage location [1].

Such SHM systems, if appropriately designed, will also allow a reduction in the downtime of assets and planned, inspection-interval based maintenance will no longer be required in favour of an on-demand maintenance programme. Safety critical structures, such as off-shore wind turbines or aircrafts, will receive the most benefit from this approach to monitoring, since their maintenance downtime represents a large part of their operative cost.

Among the SHM techniques being investigated at the moment, Acoustic Emission (AE) is considered a good candidate [2]. AE is based on the observation that materials, when undergoing some type of damage, release energy in the form of short, transient elastic waves in the ultrasound band (100 kHz – 1000 kHz). These waves propagate in the structure through the material's bulk and surface, and eventually dissipate due to various phenomena. These waves can be recorded by means of appropriate sensors, usually of the piezoelectric type [3].

AE is considered a passive Non Destructive Technique (NDT): it does not require signals to be emitted (i.e. to introduce energy in the structure) to detect damage; instead it waits for signals to be recorded by the system due to some specific process in the material. This is a major advantage of AE as it does not require to continuously scan the structure or record data in search of a potential damage. This is however also a downside, because it does not provide information about a structure when it is not loaded, unlike other NDTs (like radiography or ultrasound). In other words, the source must be active to be detected; unstressed flaws will not generate AE.

There are several causes for AE. In metallic structures, AE can arise from crack propagation and plastic deformation [4], as well as from non-detrimental phenomena such as friction and bonding relative movement, together with spurious noise sources from parts that are acoustically connected. In composite structures, AE sources are associated with the main composite failure modes; fibre breakage, matrix cracking, fibre pull-out and delamination [5]. An in-depth analysis of this activity can lead to source type identification based on waveform characteristics; this is the subject of current extensive research [6]. Especially in composite materials, AE has proved to offer interesting indications to researchers about the development of damage. Static tests, but also fatigue tests [7,8], crack propagation, bond strength tests [9], residual strength tests [10] and many others have benefitted from AE monitoring.

For all these applications, the necessity to identify different AE sources emerges. The main concern is to learn how to assess whether and when a specific failure mode occurs in a material; such research is usually aimed to increase the knowledge on failure modes of materials or structures and is directed towards the development of better damage models.

One of the advantages of AE is its ability to localise damage sources by using multiple sensors (equal or more than three for planar localisation [11]). Common planar location algorithms usually consider a uniform velocity in the whole plane; then, based on the time of arrival (ToA) of the waveforms, they compute the position by intersection of hyperbolae between sensor pairs. This algorithm is robust for homogeneous

materials, provided that the waveforms ToA is computed correctly and the velocity is known with an adequate precision. However, in anisotropic materials, such as Carbon Fiber Reinforced Polymers (CFRP), the wave velocity depends on the orientation of the wavepath with respect to the ply orientation. This makes the ToA technique prone to errors. Additionally, local features (such as holes and material local inhomogeneities) add uncertainty to the problem. To overcome this issue, a technique called Delta-T was developed [12,13]. Delta-T utilises user generated maps of ToA differences between sensors, not by defining a velocity but with a calibration grid. A HSU-Nielsen source [14] is generated at each grid point; subsequently, for each sensor pair, a ToA difference map is determined. The location algorithm then, when receiving a waveform (or, more specifically, the sensor pairs ToA differences) employs a reverse lookup on each Delta-T map and identifies the source location. This technique proved more precise than the ToA in an investigation of a metallic structure [15].

Commercial AE systems already provide some sort of data compression, by encoding the information contained in each waveform into different parameters, such as peak amplitude, frequency content, duration, energy and some others. Moreover, these parameters are thought to be linked to the kind of damage source that originated the signal. This feature would benefit a user of AE as a SHM, by providing information not only on the AE activity of a certain area of a structure, but also on the activity of specific damage modes.

In composite materials, AE can be generated in a number of ways; the main failure modes include matrix cracking, fibre-matrix debonding, fibre fracture and delaminations. There are differences in the nature of the AE signals due to the source type; this is mainly due to the in-plane or out-of-plane energy content. It is known that matrix cracking and fibre breakage initiate mostly in-plane phenomena and generate extensional waves of higher frequency, while delaminations are dominated by flexural waves of lower frequency [16].

In a delamination, the laminate separates at the interface between two layers, in some cases without indications on the surface (for example, some impacts, although not visible from the impacted surface, may hide large delaminations). Some authors suggest delaminations give rise to high amplitude signals [17], while others point out medium amplitude signals for a $\pm 45^\circ$ laminate [18]; authors generally agree on delamination signals having in general a long duration [19], but tend to include debonding within the same classification.

Matrix cracking generally occurs between fibres at the fibre-matrix interface, or as shear failures between plies. These types of matrix failures usually cause hackles, which are visible on the surface. Results have been found to be dependent on material and testing procedure, with some agreement on defining matrix cracking AE as mid-to-high amplitude and low frequency [20], but some studies report low amplitude [17,18,21] and medium frequency [22] fast decay [23] but also slow decay [24].

Finally during loading, some fibres eventually fail in tension. The expected AE signature is an abrupt energy release mechanisms, with high amplitude and fast risetime [18], as it would happen in a brittle crack phenomenon.

As discussed, early approaches based the classification of damage mechanisms on a single AE parameter, typically peak amplitude or frequency content. When trying to overcome some issues, mainly related to signal attenuation as a function of distance, multiple parameters at once have been considered [21,25]. Due to the high amount of data to be processed and difficulties in identifying patterns with traditional statistical techniques, machine learning algorithms, especially Artificial Neural Networks (ANN) have been increasingly used in this field [26–29]. Among these techniques, a previous paper by the authors [30] presented an unsupervised technique for the classification of AE signals, based on the Self Organizing Map (SOM) and the k-means clustering algorithm. The technique, for brevity referred to as *k-SOM*, also employs a number of clustering indexes to determine which is the optimal number of natural classes found in a dataset. In this way, no user input or tuning is required.

The aim of this experimental work is to obtain, analyse and identify AE signals from different damage sources. These sources should be generated in a way that they could be easily isolated from boundary effects (like edge reflections), while at the same time being in a known and distinct location. The positive identification of different damage sources by the *K-SOM* classification technique is key to separating the different contributions of the various AE modes in a real structure; for this reason, a further validation of the technique is meant to be provided by this work.

2. Experimental plan

2.1 Panel

A 500mm×500mm CFRP panel was manufactured from unidirectional pre-preg T800S carbon fibre (56.6% in volume) in epoxy resin (M21/35%/UD268/T800S, Hexcel Corporation). The final laminate consisted of eight layers, laid up as $[0/90]_{2s}$, giving a total thickness of 2.2mm, this was in line with the indications of the manufacturer (a 2.1mm thickness was expected).

To promote matrix cracking in the innermost 0° layers (3rd and 6th) a 25mm crack was introduced by cutting the fibres with a knife. Particular attention was paid when manufacturing the final lay-up to ensure that the two cracked layers were aligned (Figure 1). This would ensure matrix cracks are more likely to happen in this area as these plies are no longer supported by longitudinal fibres in the direct loading path.

(a) the entire panel

(b) detail of the cut

(c) cut plies schematic

Figure 1: CFRP panel during layup of the inner plies

The panel was then cured as per manufacturer specifications in an autoclave. The panel was subsequently C-scanned to make sure that no macroscopic defects or curing failures were present.

To allow the panel to be loaded in tension, two holes were drilled and reinforced with aluminium square tabs. This prevented crushing of the composite under tensile loading.

The tabs were bonded before cutting the holes with araldite glue; the holes were then drilled through both aluminium and the material. Another C-scan was then performed to compare with the original scan to make sure that it was not damaged during this process. The final panel geometry is shown in Figure 2.

Figure 2: Artificial crack panel after manufacturing

A schematic drawing of the specimen in the tensile machine is shown in Figure 3.

Figure 3: panel fitting in the tensile machine

2.2 AE Setup

For this test, a Vallen AMSY-4 system was used. Physical Acoustics Corporation WD (wideband) sensors were connected to Vallen AEP3 pre-amplifiers, with the gain set to 34dB. A band-pass filter between 95 kHz and 1000 kHz was used. Sampling frequency for waveforms was set to 5MHz with a set length of 4096 points, corresponding to a 819.2 μ s wavelength. Noise threshold was set to 44.9dB.

The panel was then prepared for the Delta-T location calibration. A square grid was drawn with two resolutions (Figure 2): the bigger one, 300mm×300mm wide, featured a 50mm spacing; in the central region a finer grid was drawn, with a 10mm spacing and a 100mm×100mm size. The smaller grid is used to get a more accurate location of damage in the cut plies region.

Two examples of the Delta-T maps are shown in Figure 4 (ten are created in total, one for each sensor pair). It is interesting to observe how the Delta-T technique allows for compensation of the disturbances of wave propagation around the tabs and local anisotropies in the wave velocity due to the woven material.

Figure 4: Examples of Delta-T calibration maps

2.3 Testing plan

After Delta-T calibration, the panel was fitted into the load test machine. A pin, running through each extension bar hole, connected the panel to the load test machine. The panel was then bolted into the extension bars (Figures 3 and 5). The bolts were tightened before starting the test, thus using friction to improve the load transfer between the machine and the panel. Particular care was used in making sure that the extension bars were vertical at almost-zero load. The panel fitted in the testing machine can be seen in Figure 5.

Figure 5: Panel with sensors and fitted in the testing machine

The testing plan consisted in running fixed-amplitude batches of 5000 cycles, at 1Hz; after each batch the panel was removed from the rig and C-scanned, monitoring the eventual damage growth in the panel. The load was increased after each batch if no or little AE was observed, otherwise another run was made at the same load level. Tests were run with an R ratio (min load / max load) of 0.1 to avoid compression loads and to obtain a sufficient preload in the fitting. The peak loads are summarised in Table 1.

Table 1: Peak load levels for the pre-impact phase

Batch nr.	Load (kN)	Batch nr.	Load (kN)	Batch nr.	Load (kN)
1	8	9-11	12	19	17
2	8	12-13	13	20-21	18
3-5	9	14-16	14	22	19
6-7	10	17	15	23-25	20
8	11	18	16	26	21

After a sufficient number of AE signals from the artificial crack area were collected (to allow source characterisation), the panel was then impacted with an Instron Dynatup 9250HV impact machine at an energy of 14J, in a location far from the crack but still within the loading path of the test. The impact machine, with the panel frame fitting, can be seen in Figure 6.

Figure 6: Impact machine and panel fitting

The purpose of the impact was to generate signals from both the crack and the delamination resulting from the impact.

The panel was then tested again as previous, increasing the load and C-scanning after every batch of loading (Table 2).

Table 2: Peak load levels for the post-impact phase

Batch nr.	Load (kN)	Batch nr.	Load (kN)	Batch nr.	Load (kN)	Batch nr.	Load (kN)
1	14	6	20	15	24	21-22	28
2	16	7-8	21	16-17	25	23-24	29
3	18	9-11	22	18	26	25-30	30
4-5	19	12-14	23	19-20	27	31	31

3. Results

3.1 Pre impact

During the first phase of testing, about 40 AE signals were detected from the crack region, with a good location accuracy (Figure 7). The regions around the bonded tabs also released AE signals, especially at the corners of the aluminium tabs; this was not unexpected since the stress field induced by the loading fixtures are likely to produce a concentration of stresses. Only signals from the crack region were utilised for this analysis as shown in Figure 7.

Figure 7: Location of AE events from the crack propagation test.

Also, for classification repeatability purposes, sensor 5 was considered throughout the whole test. Therefore, there are a few signals (as visible in Figure 7) that were located in the region of interest and were not recorded by sensor 5, although they are a small percent (around 2% of the total). A sample of the selected waveforms are shown in Figure 8.

Figure 8: AE events from crack region

The C-scans at the beginning and after the last batch without impact are shown in Figure 9. The central sensor (number 5) is always visible in the C-scans as a dark spot with its attached cable running to the left.

Figure 9: C-scan images of the panel central region during the crack propagation, also showing sensor location

C-scans confirm that no additional damage has been introduced during the test. No high attenuation (dark) areas are found; this confirms the absence of in-plane discontinuities, like delaminations. The crack region, below the sensor visible in the centre, appears to darken slightly, but no evidence of growth can be observed.

3.2 Post impact

After the impact, the AE activity of the panel increased significantly. Figure 10 shows AE localised events for the last batch after impact (batch 31). The test was then interrupted since it showed significant sources from the impact region. The figure also shows the selected events from this set.

Figure 10: AE events during the selected after impact batch

The location accuracy appears reduced, mainly due to the presence of the impact area which alters wave propagation path, while the undamaged calibration was retained. Nevertheless, it has to be noted that signals from the crack area have decreased in number, and moved towards the crack tips. This is a consequence of the fact that the crack region has reduced its stiffness, the stress field has been modified to increase at the sides of the crack and zones of stress concentration exist around the crack tips. Therefore, those signals may indicate some damage mechanisms happening at or near the crack tip regions. A sample of the signals coming from the delamination region is shown in Figure 11.

Figure 11: AE events from delamination region

The delamination size after impact was determined by C-scanning the panel again, as visible in Figure 12.

Figure 12: C-scan images of the panel before and after impact

A final C-scan after all fatigue testing was completed indicated that the delamination had not grown significantly (Figure 12c).

Superimposing AE data to the C-scan, it is clear that only the left border of the impacted area shows AE activity (Figure 13).

Figure 13: AE selected events superimposed to the C-scan

A possible explanation for this, considering that the delamination has not grown, would be that the active areas in the delamination are the ones that experience some type of rubbing or frictional phenomena, or in other words those areas that experience a high stress gradient, due to the particular stress field the panel is exposed to.

3.3 Classification of AE signals

Classification of the dataset yielded interesting results including identifying two classes of signals.

The parameters used for the classification are:

- Amplitude (A), in dB_{AE} (in logarithmic scale, with a reference voltage of 1mV at the sensor output);
- Duration (D), in μs ;
- Risettime (R), in μs ;
- Counts (CNTS), the number of signal zero-crossings;
- Energy (E), in eu ($1\text{eu} = 10^{-14} \text{ V}^2\text{s}$), calculated measuring the area under the signal envelope;
- Frequency center-of-gravity (FCOG), the geometric center frequency of the signal's Fast Fourier Transform (FFT) in kHz;
- Peak Frequency (FMXA), the peak of the signal's FFT in kHz.

The classification technique, presented in detail in [30], uses a Self-Organizing Map which takes as input the waveform's parameters vector, and gives as output the Best-matching unit (BMU). In this way, the SOM maps the multidimensional input to a 2-dimensional space, which is then further mapped to a number of clusters, which correspond to dataset classes. The optimal number of clusters in the dataset is chosen automatically considering a number of classification parameters.

For this dataset, the k-SOM classification technique identified two as the best number of natural classes. AE data has then been classified accordingly.

Global AE energy and activity trends (Figure 14) show that the first part, before impact (0 to 2646s), is dominated by Class 2, while Class 1 remains almost silent. Class 1 is observed at approximately 4500s, with an increasing trend, which is followed by Class 2.

Figure 14: AE activity and energy trends, after classification

All classified localised signals for the two batches considered are shown in detail in Figure 15.

Figure 15: Classified signals in the selected region

From this preliminary observation, it can be noted that the crack region holds mainly Class 2 signals, while the impacted area shows a mixture of both Classes, with Class 1 being evenly spread and Class 2 concentrating at the bottom boundary.

Energy and activity maps (Figure 16) show that Class 1 has a lower energy than Class 2, and is concentrated, as previously observed, around the impacted area and at the crack tips. Class 2 is concentrated in the middle of the crack and at the tips, and at the bottom boundary of the impacted area.

(a) Activity, class 1

(b) Activity, class 2

(c) Energy, class 1

(d) Energy, class 2

Figure 16: AE energy and activity 2D maps, by class

Considering the aforementioned time blocks, the evolution of signals is shown in Figure 17.

(a) $t=0$ to 2646s

(b) $t=0$ to 4500s

(c) $t=0$ to 5200s

(d) $t=0$ to end

Figure 17: AE events in time, classified

Here, the signal evolution indicates that, after impact (Figure 17b), a number of Class 2 events appear in the damaged region; then, a mixture of Class 1 and Class 2 signals are emitted at a similar rate.

An example of the waveforms from both classes is shown in Figure 18. Here it is clear that the classification technique is capable of separating two distinct groups of waveform shapes. Also, average parameters for the two classes are reported in Table 3.

(a) Class 1

(b) Class 2

Figure 18: waveforms from the two dataset classes

Table 3: average parameters for the two classes

	Class 1		Class 2	
	Average	Std. deviation	Average	Std. deviation
CNTS	3	4	85	41
A (dB)	49	3	69	6
E (eu)	89	151	27680	28732
R (μs)	8	20	94	126
D (μs)	25	33	810	504
FCOG (kHz)	263	38	266	59
FMXA (kHz)	224	57	174	77

4. Discussion

The AE results presented in Section 3 provided some key information regarding AE and damage detection in composites:

- Cutting the inner plies allowed the generation of an artificial flaw that favoured matrix cracking;
- The artificial crack area showed repeatable sources, as visible from the waveforms;
- A delamination induced by an impact becomes an active source of AE;
- The delamination source of this experiment contains two distinguishable classes of AE signals;
- The delamination source is active from the AE point of view even if the delamination does not grow.

When supported by ANN classification, the failure modes are correctly identified: the pre-impact phase shows only a single class of signals; when the panel is impacted, a second class appears. It is observed that in the impact region both delamination and crack signals are found.

The crack class signals seem to be more related to the region normal to the load path (matrix failing in tensile load); this is supported by the AE signals position relative to the delamination area observed in the C-scan and by the observation of almost only crack class signals in the cut ply region.

On the other hand, the delamination class signals are distributed in the delamination region, probably representing delaminated layer friction sources. Although this doesn't imply delamination growth, it provides a way to identify the delamination region, which may cause a significant reduction in compressive strength.

It was also observed that the two classes show repeatable sources, with distinct waveforms and AE parameters. In particular, matrix cracking sources show higher amplitude and with a relatively quicker decay, while delamination sources appear more continuous.

The augmentation of AE data with automatic classification information presented in this work represents an improvement for the use of AE as SHM system for carbon components. If a component is fitted with an AE sensor network and its signals are classified according to the procedure presented in this paper, the human discretion in interpreting AE trends and signals is significantly reduced if not completely removed when deciding if a component has developed a new damage mode.

An important feature to stress is, that if AE data is presented without classification data, it is not possible to discriminate whether a change in activity is related to a particular damage mode developing, or it is only a change in environmental conditions (e.g. noise). By coupling AE location data and classification information, it would be possible to separate the various contributions of the different classes, and monitor them separately both by location and in their time evolution.

This feature will benefit real-time monitoring, maintenance and also laboratory component testing, since the use of AE may give precious indications to the system operator about damage characteristics, location and evolution, without involving direct human intervention or downtime for inspection. During design of SHM-monitored parts, it will also be easier to reduce the safety factors involved (and thus the weight of the structure), since a SHM technique that gives precise information on each damage mode evolution reduces the uncertainties which usually lie exactly on damage modes evolution models, and contribute to decreasing inspection intervals because of this uncertainty. With such issues reduced, the inspection intervals might be reduced dramatically, relying on SHM alarms to trigger direct, localized and focussed maintenance.

5. Conclusions

This experimental work presented a way of generating two distinct artificial AE signal sources in a CFRP plate, namely one related to matrix cracking phenomena and a second one related to impact-induced in-plane delamination. A neural network based, fully automated classification technique proved to be effective in identifying these two different sources and to correctly separate them. This was supported by visual observation and ultrasonic C-scanning.

The AE technique, supported both by advanced location algorithms (namely the Delta-T technique) and automatic classification methods (the k-SOM classifier), proved to allow to monitor in real-time CFRP structures under fatigue load, and could be easily made capable of automatically identifying the onset of a novel damage mode in real-time.

Criteria for rejection or acceptance of parts (i.e. defining alarm levels and assessing false alarm probabilities) have yet to be investigated deeply. Also, the applicability of the classification technique to real-time AE data classification without having to consider the entire dataset is being evaluated at the moment.

Acknowledgements

The authors would like to acknowledge the support of Cardiff University - School of Engineering laboratories, facilities and staff for the support given during the experimental part of this work.

References

- [1] Worden K, Farrar CR, Manson G, Park G. The fundamental axioms of structural health monitoring. *Proc R Soc A Math Phys Eng Sci* 2007;463:1639–64.
- [2] Miller RK, McIntire P. NDT Handbook vol. 5, American Society for Nondestructive Testing; 1987, p. 652.
- [3] Finleyson RD. Handbook of Nondestructive Evaluation, McGraw-Hill Companies; 2003, p. 10.1–10.39.
- [4] Huang M, Jiang L, Liaw PK, Brooks CR, Seeley R, Klarstrom DL. Using Acoustic Emission in Fatigue and Fracture Materials Research. *JOM* 1998;50.
- [5] Hamstad MA. Thirty Years of Advances and Some Remaining Challenges in the Application of Acoustic Emission to Composite Materials. In: Kishi T, Ohtsu M, Yuyama S, editors. *Acoust. Emiss. Beyond Millenn.*, Elsevier, Oxford, UK; 2000, p. 77–91.
- [6] Wang X, Zhang H-P, Yan X. Classification and identification of damage mechanisms in polyethylene self-reinforced laminates by acoustic emission technique. *Polym Compos* 2011;32:945–59.
- [7] Caruso C, Lonetti P, Manna A. Dynamic Crack Propagation in Fiber Reinforced Composites. *Proc. COMSOL Conf.* 2009 Milan, 2009.
- [8] Jessen SM, Plumtree A. Fatigue damage accumulation in pultruded glass/polyester rods. *Composites* 1999;20:559–67.
- [9] Ireman T, Ranvik T, Eriksson I. On damage development in mechanically fastened composite laminates. *Compos Struct* 2000;49:151–71.
- [10] Caprino G, R.Teti, de Iorio I. Predicting residual strength of pre-fatigued glass fibre-reinforced plastic laminates through acoustic emission monitoring. *Compos Part B* 2005;36:365–71.
- [11] Finleyson RD. Acoustic Emission Testing. *Handb. Nondestruct. Eval.*, McGraw-Hill Companies; 2003.
- [12] Baxter MG, Pullin R, Holford KM, Evans SL. Delta T source location for acoustic emission. *Mech Syst Signal Process* 2007;21:1512–20.
- [13] Eaton MJ, Pullin R, Holford KM. Acoustic emission source location in composite materials using Delta T Mapping. *Compos Part A Appl Sci Manuf* 2012;43:856–63.
- [14] HSU NN. A mechanical AE simulator for system calibration and waveform analysis. 16th Meet. U.S. Acoust. Emiss. Work. Gr., Williamsburg, Va, United States: 1976.
- [15] Holford KM, Pullin R, Baxter MG. Modal Analysis of Acoustic Emission Signals from Artificial and Fatigue Crack Sources in Aerospace Grade Steel. *Key Eng Mater* 2005;293:217–24.
- [16] Mal A. Elastic waves from localized sources in composite laminates. *Int J Solids Struct* 2002;39:5481–94.

- [17] Huguet S, Godin N, Gaertner R, Salmon L, Villard D. Use of acoustic emission to identify damage modes in glass fibre reinforced polyester. *Compos Sci Technol* 2002;62:1433–44.
- [18] Zhuang X, Yan X. Investigation of damage mechanisms in self-reinforced polyethylene composites by acoustic emission. *Compos Sci Technol* 2006;66:444–9.
- [19] Ramirez-Jimenez CR, Papadakis N, Reynolds N, Gan TH, Purnell P, Pharaoh M. Identification of failure modes in glass/polypropylene composites by means of the primary frequency content of the acoustic emission event. *Compos Sci Technol* 2004;64:1819–27.
- [20] Groot PJ De, Wijnen PAM, Janssen RBF. Real-time frequency determination of acoustic emission for different fracture mechanisms in carbon/epoxy composites. *Compos Sci Technol* 1995;55:405–12.
- [21] Godin N, Gaertner SHR, Salmon L. Clustering of acoustic emission signals collected during tensile tests on unidirectional glass/polyester composite using supervised and unsupervised classifiers. *NDT E Int* 2004;37:253–64.
- [22] Refahi Oskouei A, Ahmadi M. Acoustic Emission Characteristics of Mode I Delamination in Glass/Polyester Composites. *J Compos Mater* 2010;44:793–807.
- [23] Laksimi A, Benmedakhene S, Bounouas L. Monitoring acoustic emission during tensile loading of thermoplastic composites materials. *Proc. ICCM 12 Eur.*, 1999.
- [24] Godin N, Huguet S, Gaertner R. Influence of hydrolytic ageing on the acoustic emission signatures of damage mechanisms occurring during tensile tests on a polyester composite : Application of a Kohonen's map. *Compos Struct* 2006;72:79–85.
- [25] Grosse C, Reinhardt H, Dahm T. Localization and classification of fracture types in concrete with quantitative acoustic emission measurement techniques. *NDT E Int* 1997;30:223–30.
- [26] Leone C, Caprino G, de Iorio I. Interpreting acoustic emission signals by artificial neural networks to predict the residual strength of pre-fatigued GFRP laminates. *Compos Sci Technol* 2006;66:233–9.
- [27] De Oliveira R, Marques AT. Health monitoring of FRP using acoustic emission and artificial neural networks. *Comput Struct* 2008;86:367–73.
- [28] Bhat C, Bhat MR, Murthy CRL. Acoustic emission characterization of failure modes in composites with ANN. *Compos Struct* 2003;61:213–20.
- [29] Sause MGR, Gribov A, Unwin AR, Horn S. Pattern recognition approach to identify natural clusters of acoustic emission signals. *Pattern Recognit Lett* 2012;33:17–23.
- [30] Crivelli D, Guagliano M, Monici A. Development of an artificial neural network processing technique for the analysis of damage evolution in pultruded composites with acoustic emission. *Compos Part B* 2014;56:948–59.